

Message Text

LIMITED OFFICIAL USE

PAGE 01 BUCHAR 03489 091537Z

66

ACTION FBO-08

INFO OCT-01 EUR-06 ISO-00 A-01 /016 W

----- 020626

R 091511Z AUG 74

FM AMEMBASSY BUCHAREST

TO SECSTATE WASHDC 9641

INFO AMEMBASSY VIENNA

AMCONSUL BERLIN

LIMITED OFFICIAL USE BUCHAREST 3489

FOR A/FBO CLEM RALSTON AND EUR/EX JOAN CLARK

VIENNA FOR REGIONAL B/F OFFICER

BERLIN FOR STANGE

EO 11652: N/A

TAGS: ABLD, RO

SUBJECT: NEW CHANCERY & RESIDENCE: MAINTENANCE OF PRESENT CHANCERY

1. EMBASSY APPRECIATES FBO WILLINGNESS TO SEND AREA OFFICER PAUL STANGE TO BUCHAREST AT END OF HIS STAY IN BERLIN ABOUT AUGUST 14. TO DATE, HOWEVER, WE HAVE NOT RECEIVED CLEARANCE FROM MAYOR'S OFFICE TO VIEW NEW AREA; WE ARE FOLLOWING-UP NOW, AND HOPE TO HAVE POSITIVE RESPONSE SOON, HOPEFULLY BEFORE AUGUST 14.

2. IN REGARD TO VISIT BY FBO TECHNICIAN TO INSPECT WIRING AND MAKE RECOMMENDATIONS FOR OFFICE SPACE USE, FOLLOWING DEVELOPMENTS HAVE OCCURRED SINCE OUR LAST REFTEL:

A) WE HAVE HAD AN OVERLOAD PROBLEM ON ONE PHASE OF A FUSIBLE DISCONNECT, BURNING OUT THE DISCONNECT EVEN THOUGH IT WAS PROPERLY FUSED. ACCORDING TO OUR OBSERVATIONS WE ARE OPERATING AT UPPER LOAD LIMIT ON ENTIRE SYSTEM.

B) NEW CRACKS HAVE APPEARED IN RECENTLY SHORED UP EMBASSY WING. WE HAVE DETERMINED FROM OUR OWN OBSERVATION THAT THESE ARE PRIMARILY SURFACE CRACKS (ABOUT ONE TO TWO INCHES DEEP) IN NON-LOADBEARING PARTITION WALL, AM HAVE POSSIBLY BEEN CAUSED BY RECENT MILD EARTH

LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 BUCHAR 03489 091537Z

TREMORS. NEVERTHELESS WE WOULD APPRECIATE EXPERT EVALUATION

OF THIS STRUCTURAL SITUATION AS SOON AS POSSIBLE.

3. IN ADDITION TO EVENTS DESCRIBED IN PARA 1, WE WILL BE FORCED,
BY END OF AUGUST AT LATEST, TO MAKE SOME MOVES IN MAIN BUILDING, USING

ATTIC SPACE, TO ACCOMMODATE NEWLY ASSIGNED STAFF. WITHOUT
FBO ASSISTANCE AND RESOURCES. WE WOULD APPRECIATE, IN
VIEW OF ABOVE CONSIDERATIONS, AN EARLY REPLY TO POSSIBLE
TIMING OF FBO TECHNICIANS VISIT.

BARNES

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptoning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 09 AUG 1974
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: golinofr
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1974BUCHAR03489
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: D740218-1053
From: BUCHAREST
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1974/newtext/t19740861/aaaacapl.tel
Line Count: 71
Locator: TEXT ON-LINE, ON MICROFILM
Office: ACTION FBO
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators:
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: n/a
Review Action: RELEASED, APPROVED
Review Authority: golinofr
Review Comment: n/a
Review Content Flags:
Review Date: 19 MAR 2002
Review Event:
Review Exemptions: n/a
Review History: RELEASED <19 MAR 2002 by shawdg>; APPROVED <15 MAY 2002 by golinofr>
Review Markings:

Declassified/Released
US Department of State
EO Systematic Review
30 JUN 2005

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: NEW CHANCERY & RESIDENCE: MAINTENANCE OF PRESENT CHANCERY
TAGS: ABLD, RO
To: STATE
Type: TE
Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005